










AirBrakeSystems

Haldex Slack Adjuster Repair Parts

	 <p>Many variations exist -please quote 3 digit number stamped into plate</p>
<p>HSK 1.3S - Repair Kit (with Worn, Clutch, Rack and Bushes)</p>	<p>HSK 2.XXX - Control Plates</p>

 <p>HSK 1.8 Rack</p>		 <p>SF1799ASA Grease - 1 Kg</p>
<p>HSK 1.9 Worm Screw</p>		

	 <p>Bushes</p>				
<p>HSK 1.7 End Cover</p>	<p>HSK 1.2 -- 14x19mm HSK 1.2A - 12.7x19mm HSK 1.2C - 16x20mm</p>	<p>HSK 2.001 Control Plate Gasket</p>	<p>HSK 3 Bleed Nipple Straight</p>	<p>HSK 3.1 Bleed Nipple 45 Degrees</p>	<p>HSK 2 Control Plate Plastic Insert</p>

	<p>HSK 1.4B - 8 spline HSK 1.4A - 10 spline HSK 1.4C - 19 spline HSK 1.4D - 20 spline HSK 1.4F - 26 spline HSK 1.4E - 27 spline HSK 1.4H - 28 spline HSK 1.4I - 36 spline HSK 1.4G - 37 spline</p>	<p>Fiat, Iveco (old) DAF, Volvo, Scania MAN, Merc (old) ZF axles MAN (old), Kassbohrer MAN, Mercedes(new) RVI, SAE Rockwell, Seddon Atkinson Rockwell, RVI, Mack Fruehauf, Propar</p>	<table border="1"> <thead> <tr> <th data-bbox="1002 1809 1152 1841">TOOL KIT</th> <th data-bbox="1152 1809 1439 1841">Content</th> </tr> </thead> <tbody> <tr> <td data-bbox="1002 1841 1152 2020">  </td> <td data-bbox="1152 1841 1439 2020">  </td> </tr> </tbody> </table>	TOOL KIT	Content		
TOOL KIT	Content						
							
<p>HSK 1.4* - Splines</p>			<p>HSK 4 - Tool Kit (with Manual)</p>				